

Arm SystemReady IR v1.0: Errata Document

Company: NXP**System:** NXP i.MX8M Mini EVK**SoC Family:** i.MX8M Mini**Firmware Version:** NXP 2021 Q2 pre-release firmware , version LF 5.10.35
2.0.0 rc1**ACS Version:** ACS-IR v0.8 BETA 0**BSA Details:** BSA v1.0**EBBR Details:** EBBR v2.0.1**BBR Details:** BBR v1.0**Arm SystemReady certification:** SystemReady IR v1.0 (level 0)**List of Errata****Errata #1 - Debian GRUB installation must be finalized manually**

During Debian installation, the "Install the GRUB boot loader" step will fail and manual intervention is necessary to make the installed system bootable.

Select "Execute a shell" and do:

```
# chroot /target
# update-grub
# mkdir /boot/efi/EFI/BOOT
# cp -v /boot/efi/EFI/debian/grubaa64.efi /boot/efi/EFI/BOOT/bootaa64.efi
```

Exit the chroot and the shell to return to the installer and select the "Continue without boot loader" step to finish installation.